## PORTWEST. | USER INFORMATION

REF- 2USP



EN ISO 20471 RIS-3279

**CERTIFIED** 

www.portwest.com/declarations

	Α	D
	CM	CM
SHORT	152-164	74
REG	164-176	79
TALL	176-188	84
XTALL	188-202	92



В	INCHES	CM	EURO
XS	32"-34"	80-88	40-44
S	36"-38"	92-96	46-48
M	40"-41"	100-104	50-52
L	42"-44"	108-112	54-56
XL	46"-48"	116-124	58-62
XXL	50"-52"	128-132	64-66
3XL	54"-55"	136-140	68-70
4XL	56"-58"	144-148	72-74
5XI	60"-64"	152-160	76-80

c	INCHES	CM	DE	FR
XS	26-28	68-72	42-44	34-36
S	30-32	76-80	46-48	38-40
M	33-34	84-88	50	42-44
L	36-38	92-96	52-54	46-48
XL	40-41	100-104	56	50-52
XXL	42-44	108-112	58-60	54-56
3XL	46-47	116-120	62	58-60
4XI	48-50	124-128	64-68	62-64

#### MANUFACTURER

PROFHUESI, ПРОИЗВОДИТЕЛ, PROIZVOBAČ, VÝROBCE, TOOTIA, VALMISTAJA, FABRICANT, HERSTELLER, KATAZKEYAZTHZ, GYÁRTÓ, FABBRICANTE, RAŽOTÁJS, GAMINTOJAS, PIPOHJBOQUITEN, PRODUZHAJEC, TILLYERAKRE, ÚBERTÍC, BUPOGHMKA, PROJZVAJALEC, TILLYERAKRE, ÚBERTÍC, BUPOGHMKA

PORTWEST LIMITED, Westport, Co Mayo, Ireland

#### **TEST HOUSE**

AGJEKISA ETESTIMIT, RAGORATORIA SA AISIMITARIAE, ESPITIAA KUĆA, ZRUŠEBNI DŪM, TESTHUS, TEST MAJA, TESTAJA, ORGANISMA NOTIFIE, TESTIERINJE, SOMH AOKIMOM, TEST HOUSE, LABORATIORI, TEST HAVING ISTAJAE, TESTAVIMO ISTAJAE, TEST KYRĀ, TESTORA, LABORATORIUM BADAJAÇE, CASA DE TESTE, KOISINTATĒRISHĀÜ (HEPT, ESPITIAA KUĆA, CERTIFIKĀCĪV) GOGĀN, TESTNA HĪSA, LABORATORIO DE FISANON, TESTILIS, TEST KIRĪLIKI KUR MORPOSVARIJAHĀVI GOGĀN, TESTNA HĪSA,

INTERTEK The Warehouse, Brewery Lane, Leigh, WN7 2RJ UK

Notified body number: 0362

Wyndham Way, Telford Way, Kettering, Northamptonshire,

NN16 8SD, United Kingdom Notified body number: 0321 Bracetown Business Park, Clonee, Dublin 15, D15 YN2P Ireland

Notified Body: 2777

VARTEST Vartest Laboratories, Inc., 19 West 36th Street,

10th Floor New York, NY 10018, ISO/IEC 17025 Testing Certificate No.

through A2LA is 2180.01

AITEX Plaza Emilio Sala 1, 03801 Alcoy, Alicante, Spain

Notified body number: 0161

Institut fur Okologie, Technik und Innovation GmbH, Spengergasse

20 1050 Vienna, Austria Notified body number: 0534

ΕN

Please read these instructions carefully before using this safety clothing. You should also consult your safety officer or immediate superior with regard to suitable garments for your specific work situation. Store these instructions carefully so that you can consult them at any time.



Refer to the product label for detailed information on the corresponding standards. Only standards and icons that appear on both the product and the user information below are applicable. All these products comply with the requirements of Regulation (EU 2016/425).



### ISO 13688:2013 Protective Clothing

General Requirements This European
Standard specifies general requirements
for ergonomics, ageing, sizing, marking
of protective clothing and for information
supplied by the manufacturer.

- A= Recommended height range of wearer B= Recommended chest girth of wearer
- C = Recommended waist girth of wearer
- D= Recommended inside leg measurement of wearer
- \_\_\_\_\_



# EN ISO 20471:2013 + A1:2016, High Visibility Warning Clothing signalling the users presence during day and night (see label)

- X Classifications (EN ISO 20471:2013 + A1:2016) X Class for the fluorescent and reflective surface - 3 levels
- X Class 1 Minimum level traffic speeds <30km/h Class 2 -Intermediate level traffic speeds <60km/h Class 3 -Highest level traffic speeds >60km/h

Tumble dry normal



#### RIS-3279-TOM Issue 1 (2016): Railway Industry Standard RIS-3279-TOM Issue 1 has replaced GO/RT 3279

Railway Industry Standards (RIS) are mandatory on all members of the Railway Group and apply to all relevant activities.

Limitations of use (EMSD 2047-2013 + A1-2016, BS 3279 & ANJ/SSA 170-2015): heaps were the gament fastened. Keep clean: Sould the High Visibility properties of this gament become irrecoverably solided or contaminated, replace with a new one. This gamment is suitable for wear during an entite working day and contains no trais cubstance shat can affect health adveneyly in any other way, No allengic reactions due to skin creater with his gamment are hown. Do not attempt to repair damaged gamments. All gamments should be discarded safety. The coffring solvoid on the aftered or fitteed with creat labels or loops. The clothing should only be worn in situations for which it is intended.

Limitations of use (RIS 3279): Class 1 trousers claiming RIS 3279 Compliance are required to be worn with a RIS 3279 upper body garment.

#### Available Size & Selection:

Fit according to correct chest and waist size, refer to size chart. These garments have built in allowance for comfort and to allow the garment to be worn over medium bulky clothing.

#### Storage:

DO NOT store in places subject to direct or strong sunlight. Store in clean, dry conditions.

After-care:The manufacturer will not accept liability for garments where care labels have been ignored, defaced or removed.

#### Fibre Content Label:

Refer to garment label for corresponding content details. **Warning:**Where there is a hood, peripheral vision and hearing may be impaired.

#### Retroreflective tape and labels:

Retureflective tage or abbels should not be inned! Please refer to the gammen label for the number and wash cycles claimed. The state maximum number of cleaning cycles is not the only factor related to the lifetime of the gamment. The lifetime will also beginned ou usage, care storage, etc. Gammest should be discarded when the princtive qualifies no longer apply eg. 1. Maximum number of washes is reached. 2. The material has been damaged either by lading or has been torus. 3. The reflective qualities of the tage have faded. 4. Gamment is permanently solider, cardickly Junto of the waysh paraded.

Wash Care Labels: Refer to garment label for corresponding washing details.

30°	Max temp 30°C, mild process	1	Line dry	MAX	Maximum
40°	Max temp 40°C, mild process	Ш	Drip line dry	50x	50 Washes
40°	Max temp 40°C, normal process	$\bowtie$	Do not iron	MAX 25v	Maximum 25 Washes
60°	Max temp 60°C, normal process	$\overline{}$	Iron max 110°C	MAX	Maximum
×	Do Not Bleach	<u></u>	Iron max 150°C	<b>12</b> x	12 Washes
	Do not tumble dry	×	Do not dry clean	MAX	Maximum
0	Tumble dry low	(P)	Professional dry clean	<b>5</b> x	5 Washes

SATRA

OT