



Sir Safety System S.p.A. Single-member company Wholly-owned subsidiary of Sir Holding Srl Via dei Fornaciai, 9 - Santa Maria degli Angeli 06081 Assisi - Perugia - Italy Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548 Viale Europa 74 20090 Cusago Milano Tel. +39 02.90394575 Fax +39 02.90394441

export@sirsafety.com www.sirsafety.com

Storage and cleaning

Quality Management System Certificate UNI EN ISO 9001:2015

Name: MISTRAL COLOR SHORT JACKET

Code: MC3519HD

MC35 HIGH VISIBILITY CLOTHING - SUMMER

## Description

High visibility short jacket made of Mistral fabric 55% cotton and 45% polyester, weight 245 g/m with shirt collar, concealed five-button closure, two chest pockets with flap and Velcro, one of which tridimensional with pen holder, and double stitched seams for high resistance. Top part in high visibility fabric and bottom part, bottom of sleeves, collar and pocket flaps in non-fluorescent fabric. It features two loops of reflective bands around the sleeves and chest.

- The Mistral range guarantees excellent breathability thanks to the high percentage of cotton.
- Weight of 245 g/m, ideal for the summer.
- The fabric surface enhances the ability to repel liquid and dirt.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequentamendments.

EN ISO 20471

Class 2:

Dexterity

A0.50 m fluorescent material;

A0.13 m reflective material.

Class 3 in combination with articles MC3521 and MC3522. V@ÁUÒSUË/ÒÝíÁ&∧¦cãa&æe¢Á;Áa@Á;æājÁ;čo¦Áæà¦a&Áa;Á under review.





Category	Colours	Available Sizes
II	HI-VIS ORANGE/BLUE	44 - 70
Quantity/Carton	EC Standards	Important Information
	EN ISO 20471  Class:2	General and Road Construction, Road sign work, Road and plants maintenance, Emergency response companies.
		The performances of the garment are guaranteed when it is correctly worn and fastened.
20		Keep in a cool dry place, far from heat sources and direct light.  Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.
		We recommend to follow the washing instructions. Resistance up to 50 washings.