Technical specs

PHVES - PHVES

Name:

PANOSTYLE HIGH VISIBILITY WORKING JACKET IN COTTON / POLYESTER

<u>Size:</u>

S - M - L - XL - XXL - XXXL

Colour:

Fluorescent Orange-coloured / Navy Blue - Fluorescent Yellow / Navy Blue



Description:

PANOSTYLE high-visibility working jacket. Elasticated cuffs. 2 pockets. High visibility : Class 2 - Silver colour - Shoulder-belt and parallel assembly.

Materials:

54% Cotton / 46 % Polyester - 260 g/m². Retroreflecting stripes 100% polyester.

Instructions for use:

Class 2 signalling garment of PANOSTYLE HIGH VISIBILITY serie to be perfectly seen during outdoor day work as well as night work and in the light of the headlights.

Limits to use:

Do not use outside of its field of use as defined in the instructions for use above. Before putting on this item of clothing, check that it is not dirty or worn; this will reduce its effectiveness. Ensure that the grey retro-reflective band is placed on the outside of the item of clothing and close the garment in order to be in continuity with this last. It must not bear any agent which could reduce its visible surface. This article of clothing does not contain any substance known to be carcinogenic, toxic, or likely to cause allergies in sensitive people. If the protective material is damaged dispose of the item of clothing.

Instructions for storage:

Store in the original packaging away from light and dampness.

Instructions for cleaning / maintenance:

Wash inside out. Maximum temperature 40°C (numbers authorized maximum washing, see label of composition of clothing), mechanical action reduced, rinsing at gradually decreasing temperature (cool down), spinning reduced. Do not use chlorine-based bleach. Iron at a maximum sole-plate temperature of 150°C, Steam-ironing may be risky. Do not dry-clean, no stain removal with solvents. Do not tumble dry. Do not use high alcalin stain remover, neither detergents with solvents or microemulsions, or bleaching agents.

Performances :

This parka complies with the European directive 89/686, notably regarding ergonomics, innocuousness, comfort, ventilation and flexibility, and with EN340:2003 and EN471:2003/A1:2007 (2,2) high-visibility warning clothing for professional use European standard.

• EN471:2003 /A1:2007

High-visibility warning clothing for professional use - Test methods and requirements



2 : Garment class (1 to 3)
2 : Level of retroreflective material performance (1 to 2)



DELTA PLUS GROUP La Peyrolière - B.P. 140 - 84405 APT Cedex - France www.deltaplus.fr

